MP 56.70



Date: 9/20/2024

Notes: Project material has been pulled back within staked approved workspaces at MP 56.70.

MP 56.70



Date: 9/20/2024

Notes: Project material has been pulled back within staked approved workspaces at MP 56.70.

MP 57.10



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.10. The follow-up photo was taken on 9/23/2024.

MP 57.10



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.10. The followup photo was taken on 9/23/2024.

MP 57.10

● 46.368408°, -96.660402° ±13ft ▲ 952ft



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.10. The followup photo was taken on 9/23/2024.

MP 57.10



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.10. The followup photo was taken on 9/23/2024.

MP 57.99

© 46.355554°, -96.663268° ±13ft ▲ 955ft

Date: 9/19/2024

Notes: Project material is being pulled back within staked approved workspaces at MP 57.99.

MP 57.99



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.99. The followup photo was taken on 9/23/2024.

MP 57.99



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.99. The followup photo was taken on 9/23/2024.


MP 57.99



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 57.99. The followup photo was taken on 9/23/2024.

MP 58.50



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 58.50. The followup photo was taken on 9/23/2024.

MP 58.50



Date: 9/19/2024

Notes: On 9/19/2024, Project material was pulled back within staked approved workspaces at MP 58.50. The followup photo was taken on 9/23/2024.

Problem Area

Date: 9-17-2024 Location: MPs 11.64 thru 18.18 Authorized workspace limits not visibly marked per Plan II.B.3. Correct within 7 days.

Corrective Action

The right-of-way markers from MPs 11.64 thru 18.18 were reinstalled by September 22, 2024.




Date: 9/21/2024

Notes: Looking across Valve Site 2 pad and re-installed right-of-way markers at MP 11.70.

MP 11.70

MP 15.74

© 217°SW (T) LAT: 46.746496 LON: -96.989726 ±13ft ▲ 922ft



Notes: Re-installing right-of-way markers MP 15.74.



MP 15.88

© 268°W (T) LAT: 46.745580 LON: -96.989547 ±13ft ▲ 919ft



Date: 9/21/2024

Notes: Re-installed right-of-way markers at MP 15.88.



Date: 9/22/2024

Notes: On 9/22/2024, reinstalled right-ofway markers at MP 17.66. The followup photo was taken on 9/23/2024.

MP 17.75



Date: 9/22/2024

Notes: On 9/22/2024, reinstalled right-ofway markers MP 17.75. The followup photo was taken on 9/23/2024.



Date: 9/22/2024

Notes: On 9/22/2024, reinstalled right-ofway marker at MP 18.11. The followup photo was taken on 9/23/2024.

Problem Area

Date: 9-18-2024 Location: MP 47.4 Temporary ECDs not installed along resources per Procedures V.B.10.b. Correct within 2 days.

Corrective Action

On September 19, 2024, erosion control devices (straw wattles and silt fence) were installed adjacent to the resources (wetland wrid003e and waterbody srid001e) along the construction right-of-way. No sediment has been transported off the construction right-of-way into these resources.

MP 47.40



Date: 9/19/2024

Notes: Installed erosion control devices at MP 47.40.

MP 47.40



Date: 9/19/2024

Notes: On 9/19/2024, installed erosion control devices at MP 47.40. The followup photo was taken on 9/21/2024.

MP 47.40



Date: 9/19/2024

Notes: On 9/19/2024, installed erosion control devices at MP 47.40. The followup photo was taken on 9/21/2024.

MP 47.40



Date: 9/19/2024

Notes: On 9/19/2024, installed erosion control devices at MP 47.40. The followup photo was taken on 9/21/2024.