

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

March 27, 2024

Debbie-Anne Reese, Acting Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 17

Dear Acting Secretary Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 16 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from March 18 to March 24, 2024.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Director, Regulatory Affairs and Transportation Services

Attachment

cc: via email

David Hanobic, FERC Environmental Project Manager

Dawn Ramsey, FERC Official Service List



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

A. Update on Federal Authorizations

WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.

B. Construction Status - Pipeline Facilities

• The Environmental Inspector provided onsite environmental training, as needed.

TABLE 1-1 Wahpeton Expansion Pipeline ¹

Work Completed during Reporting Period:

- Completed construction of pipe pillows within contractor yard.
- Maintained graveled access roads and fencing around Wetland wcan001e within contractor yard.
- Began receiving construction pipe within contractor yard.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading	<1%	<1%	Completed construction of pipe pillows in contractor yard.
Stringing	0%	0%	
Bending	0%	0%	
Welding	0%	0%	
Joint Coating	0%	0%	
Ditching	0%	0%	
Lowering	0%	0%	
Backfill	0%	0%	
Bores	0 of 72	0 of 72	
Cleanup	0%	0%	
Seeding	0%	0%	
Final Tie-in and Commissioning	0%	0%	
Hydrostatic Testing	0 of 1	0 of 1	
Appurtenant Facilities ²			
Block Valve #1 and Pig Launcher / Receiver #1 at MP 0.0	0 of 2	0 of 2	
Cleanup/Restoration	0%	0%	
Block Valve #2 and Pig Launcher / Receiver #2 at MP 11.6	0 of 2	0 of 2	
Cleanup/Restoration	0%	0%	
Block Valve #3 at MP 23.4	0 of 1	0 of 1	
Cleanup/Restoration	0%	0%	

¹ The pipeline may be constructed as one or two spreads, pending the award of the pipeline contract. If two construction spreads are used, Table 1-1 will be modified accordingly.

² Cleanup/Restoration includes backfilling and spreading of gravel.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

Block Valve #4 at MP 31.3	0 of 1	0 of 1	
Cleanup/Restoration	0%	0%	
Block Valve #5 and Pig Launcher / Receiver #3 at MP 39.5	0 of 2	0 of 2	
Cleanup/Restoration	0%	0%	
Block Valve #6 at MP 48.9	0 of 1	0 of 1	
Cleanup/Restoration	0%	0%	
Block Valve #7 and Pig Launcher / Receiver #4 at MP 60.5	0 of 2	0 of 2	
Cleanup/Restoration	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

• Continue receiving construction pipe at the 4 Suns contractor yard.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024



Date: 3/18/2024

Location: 4 Suns Contractor Yard.

Notes: Repaired fencing around delineated boundaries of Wetland wcan001e due to high winds.



Date: 3/18/2024

Location: 4 Suns Contractor Yard.

Notes: Continued construction of

pipe pillows.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024



Date: 3/18/2024

Location: 4 Suns Contractor Yard.

Notes: Continued to clean and remove excess gravel at west entrance into contractor yard.



Date: 3/19/2024

Location: 4 Suns Contractor Yard.

Notes: Completed construction of

pipe pillows.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024



Date: 3/20/2024

Location: 4 Suns Contractor Yard.

Notes: Completed construction of

pipe pillows.



Date: 3/21/2024

Location: 4 Suns Contractor Yard.

Notes: Storage of construction

pipe.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024



Date: 3/22/2024

Location: 4 Suns Contractor Yard.

Notes: Storage of construction

pipe.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

C. Construction Status - Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station Work Completed during Reporting Period: No work was completed during this reporting period. Activity Total % % of Total Job Comments **Completed This** Completed Period 0% Install Aboveground Station Piping 0% Install Belowground Station Piping 0% 0% Cleanup / Restoration3 0% 0%

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Landowner issues: None					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

³ Final cleanup and restoration will be in conjunction with Block Valve #1 and Pig Launcher / Receiver #1 within the compressor station yard.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	0%	
Concrete Work	0%	0%	
Install Aboveground Piping	0%	0%	
Install Belowground Piping	0%	0%	
Install Buildings	0%	0%	
Cleanup / Restoration ⁴	0%	0%	
Install Security Fence	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Landowner issu	Landowner issues: None					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action		

⁴ Final cleanup and restoration will be completed in conjunction with Block Valve #3 within the border station yard.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	0%	
Concrete Work	0%	0%	
Install Aboveground Piping	0%	0%	
Install Belowground Piping	0%	0%	
Install Buildings	0%	0%	
Cleanup / Restoration ⁵	0%	0%	
Install Security Fence	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

⁵ Final cleanup and restoration will be completed in conjunction with Block Valve #7 and Pig Launcher / Receiver #4 within the border station yard.



Project Status Report No. 17 Reporting Period: 3-18-2024 – 3-24-2024

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

None during reporting period.