

Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/03/2024

Location: Sta. No. 1253+27

Notes: Looking south across construction right-of-way. Bore 32 of the Sheyenne River (scab006p)

in background.



Date: 11/03/2024

Location: Sta. No. 1304+00

Notes: Looking north across construction right-of-way and additional temporary workspace for Bore 33. Bore 32 of the Sheyenne River (scab006p) in background.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/03/2024

Location: Sta. No. 1309+00

Notes: Looking south across construction right-of-way and additional temporary workspace

for Bore 33.



Date: 11/04/2024

Location: Sta. No. 1401 +00

Notes: Looking north across construction right-of-way.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/04/2024

Location: Sta. No. 1406 +00

Notes: Looking south across construction right-of-way.



Date: 11/04/2024

Location: Sta. No. 1459 +00

Notes: Looking west across construction right-of-way and additional temporary workspace

for Bore 35.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/04/2024

Location: Sta. No. 1459 +00

Notes: Looking east across construction right-of-way and additional temporary workspace

for Bore 35.



Date: 11/02/2024

Location: Sta. No. 1708 +87

Notes: Looking north across construction right-of-way and additional temporary workspace

for Bore 40.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 1945 +00

Notes: Looking southwest across construction right-of-way and additional temporary workspace

for Bore 45.



Date: 11/02/2024

Location: Sta. No. 2040+00

Notes: Looking northeast across construction right-of-way and additional temporary workspace

for Bore 47.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 2092+00

Notes: Looking east across construction right-of-way and additional temporary workspace

for Valve Site 5.



Date: 11/02/2024

Location: Sta. No. 2166 +00

Notes: Looking north across construction right-of-way.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 2238 +00

Notes: Looking west across construction right-of-way.



Date: 11/02/2024

Location: Sta. No. 2331 +00

Notes: Looking south across construction right-of-way and additional temporary workspace

for Bore 55.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 2346 +00

Notes: Looking south across construction right-of-way and additional temporary workspace

for Bore 56.



Date: 11/02/2024

Location: Sta. No. 2399 +00

Notes: Looking north across construction right-of-way and additional temporary workspace

for Bore 58.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 2742 +00

Notes: Looking east across construction right-of-way and additional temporary workspace

for Bore 65.



Date: 11/03/2024

Location: Sta. No. 2925 +00

Notes: Looking northwest across construction right-of-way.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024

C. Construction Status - Aboveground Facilities

TABLE 2-1 Modifications at Mapleton Compressor Station

Work Completed during Reporting Period:

• No work was completed during this reporting period.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Install Aboveground Station Piping	0%	100%	
Install Belowground Station Piping	0%	100%	
Cleanup / Restoration ⁶	0%	100%	

Work Planned for next Reporting Period and Schedule Changes:

No work is planned for the next reporting period.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Landowner issues. None				
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁶ Final cleanup and restoration will be in conjunction with Block Valve #1 and Pig Launcher / Receiver #1 within the compressor station yard.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024

TABLE 2-2 MDU- Kindred Border Station

Work Completed during Reporting Period:

• Continued cleanup / restoration activities.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	98%	7/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ⁷	5%	95%	
Install Security Fence	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

• Begin installation of security fence.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action

⁷ Remaining initial site work and final cleanup and restoration will be completed in conjunction with Block Valve #3 within the border station yard. Spreading of remaining gravel estimated to be completed by 11/27/2024 upon completion of valve setting painting and fence installation.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/02/2024

Location: Sta. No. 1230+00 and

Access Road 26.

Notes: Installed culvert at approved access road to Valve Site 3 and MDU-Kindred Border

Station.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024

TABLE 2-3 MDU- Wahpeton Border Station

Work Completed during Reporting Period:

• Continued cleanup / restoration activities.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Initial Site Work	0%	98%	8/
Concrete Work		100%	
Install Aboveground Piping		100%	
Install Belowground Piping		100%	
Install Buildings		100%	
Cleanup / Restoration ⁸	15%	95%	
Install Security Fence	0%	0%	

Work Planned for next Reporting Period and Schedule Changes:

• Begin installation of security fence.

Problem Areas, Corrective Actions and Effectiveness:

• No problem areas were identified during reporting period.

Non-Compliance Issues, Corrective Actions and Effectiveness:

• No non-compliance issues were identified during reporting period.

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:

• No non-compliance issues were identified during reporting period.

Copies included: Not applicable

Landowner Issues: None

Landowner issues: None					
Date	Name	Milepost / Alignment Sheet #	Problem/Concern	Corrective Action	

⁸ Remaining initial site work and final cleanup and restoration will be completed in conjunction with Block Valve #7 within the border station yard. Spreading of remaining gravel estimated to be completed by 11/27/2024 upon completion of valve setting painting and fence installation.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024



Date: 11/03/2024

Location: MDU-Wahpeton Border

Station.



Project Status Report No. 49 Reporting Period: 10-28-2024 – 11-03-2024

D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

• None during reporting period.