

1250 West Century Avenue Mailing Address: P.O. Box 5601 Bismarck, ND 58506-5601 (701) 530-1600

November 27, 2024

Debbie-Anne Reese, Secretary Federal Energy Regulatory Commission 888 First Street, N.E., Room 1A Washington, D.C. 20426

Re: WBI Energy Transmission, Inc. Wahpeton Expansion Project Docket No. CP22-466-000 Weekly Status Report No. 52

Dear Ms. Reese:

WBI Energy Transmission, Inc. (WBI Energy) herewith submits its Weekly Status Report No. 52 for the Wahpeton Expansion Project, in compliance with Environmental Condition 9 of the Appendix to the Federal Energy Regulatory Commission's October 23, 2023 Order Issuing Certificate in the above referenced docket.

The attached report addresses the status of the project from November 18, 2024 to November 24, 2024.

Should you have any questions or comments regarding this filing, please call the undersigned at (701) 530-1563.

Sincerely,

/s/ Lori Myerchin

Lori Myerchin Vice President, Regulatory Affairs and Transportation Services

Attachment

cc: via email David Hanobic, FERC Environmental Project Manager Dawn Ramsey, FERC Official Service List



Reporting Period: 11-18-2024 – 11-24-2024

A. Update on Federal Authorizations

• WBI Energy has obtained all necessary federal permits and authorizations required for construction of the Wahpeton Expansion Project.

B. <u>Construction Status – Pipeline Facilities</u>

- Environmental Inspectors continue to conduct onsite environmental training as needed.
- A Winter Construction and Stabilization Plan was approved to address remaining activities in winter conditions. WBI Energy will follow the FERC's Plan and Procedures along with the Winter Construction and Stabilization Plan to ensure Project areas are stabilized and erosion control devices remain effective during the winter months.

TABLE 1-1 Wahpeton Expansion Pipeline

Work Completed during Reporting Period:

- Completed drying the south portion of the pipeline.
- Continued repair and cleanup of anomaly (ACVG) locations that had been excavated for inspection.
- Continued cleanup activities, as conditions allowed.
- Seeding was suspended for the season. Remaining locations outside of cultivated cropland will be seeded in the spring of 2025.
- Continued maintenance of Project signage and erosion control devices.

Activity	Total % Completed This Period	% of Total Job Completed	Comments
Pipeline			
Clearing / Grading		100%	
Stringing		100%	
Bending		100%	
Welding		100%	
Joint Coating		100%	
Ditching		100%	
Lowering		100%	
Backfill		100%	
Bores		68 of 68	
Cleanup	<1%	85%	Cleanup will continue as conditions allow pursuant to the Winter Construction and Stabilization Plan.
Seeding ¹	<1%	25%	Included applying straw mulch over seeded areas followed by a crimper to anchor the straw mulch.

¹ Approximately 52.5 acres (out of 70 acres requiring seeding) remain to be seeded and include roadside ditches, open rangeland (Sta. Nos. 1860+00 to 1922+00, 1941+66 to 1943+26, 2398+00 to 2400+00, and 2530+00 to 2534+00), three CRP tracts (MW 148, 164, 120) and the perimeter of the valve sites. These areas will be stabilized in accordance with the FERC Plan and the Winter Construction and Stabilization Plan and seeded in the spring of 2025.



Reporting Period: 11-18-2024 – 11-24-2024

Final Tie-in and Commissioning	0%	0%	The pipeline is mechanically complete and the metering facilities have been tied in. Commissioning activities including purging and packing of the pipeline are scheduled for the week of November 25, 2024.
Hydrostatic Testing		2 of 2	
Appurtenant Facilities ²			
Valve Site #1 and Pig Launcher / Receiver #1 at MP 0.0		2 of 2	
Cleanup/Restoration		100%	
Valve Site #2 and Pig Launcher / Receiver #2 at MP 11.6		2 of 2	Valve setting needs to be painted.
Cleanup/Restoration	0%	95%	
Valve Site #3 at MP 23.4		1 of 1	
Cleanup/Restoration	0%	96%	
Valve Site #4 at MP 31.3		1 of 1	
Cleanup/Restoration	0%	50%	
Valve Site #5 and Pig Launcher / Receiver #3 at MP 39.5		2 of 2	Valve setting needs to be painted.
Cleanup/Restoration	0%	90%	
Valve Site #6 at MP 48.9		1 of 1	
Cleanup/Restoration	0%	96%	
Valve Site #7 and Pig Launcher / Receiver #4 at MP 60.5		2 of 2	
Cleanup/Restoration	0%	96%	

Work Planned for next Reporting Period and Schedule Changes:

• Complete repair and cleanup of anomaly (ACVG) locations that have been excavated for inspection.

• With current weather conditions, the anomaly locations currently excavated will be repaired, backfilled, and topsoil spread or stabilized as conditions allow. The remaining anomaly locations will be investigated when conditions allow in the spring or summer of 2025 and in coordination with the impacted landowners.

Complete remaining commissioning activities including purging and packing of the pipeline.

Continue cleanup activities as conditions allow and begin cleanup of the construction yard.

• Continue maintenance of Project signage and erosion control devices.

² Remaining pad construction and cleanup/restoration at Valve Sites 2, 3, 4, 5, 6, and 7 include spreading gravel and seeding of the valve site perimeters. The valve site perimeters will be stabilized in accordance with the FERC Plan and the Winter Construction and Stabilization Plan and seeded in the spring of 2025. Temporary fencing will be installed at Valve Sites 2, 4, 5, and 6 and the permanent fencing installed in the spring of 2025.



Problem Areas, Corrective Actions and Effectiveness:

On November 19, 2024, an approximate three- to five-gallon diesel fuel spill from an air compressor occurred at Valve Site 5 at approximately Station No. 2087+00 and impacted an approximate ten square foot area. Measures identified in the Spill Prevention, Control, and Countermeasure Plan were implemented to contain, clean up, and dispose of contaminated materials. Spill reports were completed by the Spill Coordinator and Environmental Inspector onsite, and the incident was reported using the North Dakota Department of Environmental Quality Unified Spill Reporting System. WBI Energy is the affected landowner.



Date: 11/19/2024

Location: Valve Site 5.

Notes: Discovered diesel spill.



Date: 11/19/2024

Location: Valve Site 5.

Notes: Oil booms and diapers were utilized to soak up diesel spill.



Non-Compliance Issues, Corrective Actions and Effectiveness: None

Non-Compliance Issues from Federal, State or Local Permitting Agencies and Responses:
 No non-compliance issues were identified during reporting period.
 Copies included: Not applicable

Landowner Issues: None



Date: 11/18/2024

Location: Sta. No. 430+00

Notes: Backfilling after the inspection of an anomaly found in the pipeline.





Date: 11/18/2024

Location: Sta. No. 1760+00

Notes: Seeding the construction right-of-way and additional temporary workspace for Bore 41.



Date: 11/18/2024

Location: Sta. No.1910+00

Notes: Removal of construction mats along the construction right-of-way.






Date: 11/19/2024

Location: Sta. No. 720+00

Notes: Erosion control devices on construction mat along the construction right-of-way.



Location: Sta. No. 835+00

Notes: Erosion control devices along the construction right-of-way.








Date: 11/19/2024

Location: Valve Site 7 and Sta. No. 3100+00

Notes: Installed erosion control devices along edge of Valve Site 7.



Location: Sta. No. 825+00

Notes: A pipeline anomaly investigation along the construction right-of-way.








Date: 11/21/2024

Location: Sta. No. 480+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.



Location: Sta. No. 3048+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.







Date: 11/21/2024

Location: Sta. No. 461+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.



Date: 11/22/2024

Location: Sta. No. 2880+50

Notes: Inspection of an anomaly found in the pipeline.





Date: 11/22/2024

Location: Sta. No. 2897+00

Notes: Backfilling after inspection of an anomaly found in the pipeline.



Date: 11/22/2024

Location: Sta. No. 3065+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline






Date: 11/23/2024

Location: Sta. No. 435+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.



Location: Sta. No. 485+00

Notes: Backfilling after inspection of an anomaly found in the pipeline.








Date: 11/23/2024

Location: Sta. No. 1461+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.



Location: Sta. No. 2478+00

Notes: Inspection of an anomaly found in the pipeline.







Date: 11/23/2024

Location: Sta. No. 3040+00

Notes: Spreading topsoil after inspection of an anomaly found in the pipeline.



Date: 11/24/2024 Location: Sta. No. 1825+00

Notes: Installation of fencing along the construction right-of-way.



Date: 11/24/2024

Location: Sta. No. 2532+00

Notes: Inspection of an anomaly found in the pipeline.



Date: 11/24/2024

Location: Sta. No. 2848+00

Notes: Backfilling after inspection of an anomaly found in the pipeline.



Reporting Period: 11-18-2024 – 11-24-2024

C. <u>Construction Status – Aboveground Facilities</u>

Work Completed	• • •			
No work v	vas completed duri	ng this reporting per	iod.	
Act	livity	Total % Completed Thi Period	% of Total Job s Completed	Comments
Install Aboveground	d Station Piping	0%	100%	
Install Belowground	d Station Piping	0%	100%	
Cleanup / Restorati	ion ³	0%	100%	
No proble	m areas were iden	tified during reporting	g period.	
Non-Compliance • No non-co Non-Compliance	m areas were iden Issues, Corrective ompliance issues w Issues from Feder ompliance issues w	tified during reporting Actions and Effect vere identified during	g period. tiveness: reporting period. Permitting Agencies and	Responses:
No proble Non-Compliance No non-co Non-Compliance Non-Compliance No non-co	m areas were iden Issues, Corrective ompliance issues w Issues from Feder ompliance issues w Not applicable	tified during reporting Actions and Effect vere identified during ral, State or Local F	g period. tiveness: reporting period. Permitting Agencies and	Responses:

³ Final cleanup and restoration will be in conjunction with Block Valve #1 and Pig Launcher / Receiver #1 within the compressor station yard.



Reporting Period: 11-18-2024 – 11-24-2024

A	ctivity	Total % Completed This Period	% of Total Job Completed	Comments
nitial Site Work		0%	98%	4/
oncrete Work			100%	
nstall Abovegrou	nd Piping		100%	
nstall Belowgroui	nd Piping		100%	
nstall Buildings			100%	
		00/	050/	
Cleanup / Restoration ⁴		0%	95%	
nstall Security Fe Vork Planned fo • No work	ence or next Reporting P is planned for the n	Period and Schedule ext reporting period.	100%	
No problem Areas, No problem Ar	ence or next Reporting P is planned for the n Corrective Actions lem areas were ider Issues, Corrective compliance issues v Issues from Fede compliance issues v d: Not applicable	Period and Schedule ext reporting period. and Effectiveness: tified during reporting e Actions and Effect vere identified during	100% Changes: period. iveness: reporting period. ermitting Agencies and	Responses:

⁴ Remaining initial site work, cleanup and restoration will be completed in conjunction with Block Valve #3 within the border station yard.



Reporting Period: 11-18-2024 – 11-24-2024

Activity		Total % Completed Thi Period	% of Total Job s Completed	Comments
nitial Site Work		0%	98%	5/
oncrete Work			100%	
stall Aboveground Pipir	ng		100%	
stall Belowground Pipin	ng		100%	
stall Buildings			100%	
leanup / Restoration ⁵		0%	95%	
stall Security Fence			100%	
		ext reporting period.		
Problem Areas, Correct • No problem are Non-Compliance Issues • No non-complia Non-Compliance Issues	tive Actions as were iden s, Corrective ince issues w s from Feder ince issues w applicable	and Effectiveness ified during reportin Actions and Effect ere identified during	g period. tiveness: reporting period. Permitting Agencies and F	Responses:

⁵ Remaining initial site work and cleanup and restoration will be completed in conjunction with Block Valve #7 within the border station yard.



D. Changes to Stream Crossings or Work in Environmental Sensitive Areas

TABLE 3 Changes to Stream Crossings or Work in Environmental Sensitive Areas

Schedule changes to stream crossings.

• None during reporting period.

Schedule changes for work in other environmentally sensitive areas.

• None during reporting period.